

Repair kit for basin/urinal cartridge

Ref. 753005

For TEMPOSTOP basin/urinal



DESCRIPTION

Repair kit for basin/urinal cartridge - [Ref. 753005](#)

Repair kit for TEMPOSTOP basin/urinal cartridge.
Time flow ~7 seconds.
Until 2022.

ADVANTAGES



Easy to maintain

TECHNICAL CHARACTERISTICS

Repair kit for basin/urinal cartridge - [Ref. 753005](#)

Technology

Time flow

