

Repair kit for basin/urinal cartridge

Ref. 753005

For TEMPOSTOP basin/urinal

2026 UK public price excluding VAT: £22.21

DESCRIPTION

Repair kit for basin/urinal cartridge - Ref. 753005

Repair kit for TEMPOSTOP basin/urinal cartridge.
Time flow ~7 seconds.
Until 2022.



ADVANTAGES



Easy to maintain

TECHNICAL CHARACTERISTICS

Repair kit for basin/urinal cartridge - Ref. 753005

Technology

Time flow

